



CASE STUDY

CUSTOMER

CANYON TECHNICAL

LOCATION

CALGARY, AB CANADA / JUN 2012 - MAY 2015

EQUIPMENT

ROLLER BEARING

APPLICATION

GEARBOX LUBE OIL

PROVEN RESULTS



\$7,000 SAVINGS

**REDUCED RISK OF
ROLLER BEARING
FAILURE**

CHALLENGE

Bearing tolerances are under 3 microns and contamination under 3 microns was causing damage to Timken Roller Bearings as traditional 10 micron filters are unable to remove the most damaging contamination (iron and steel) below 10 microns to sub-micron in size.

SOLUTION

Install an OEI magnetic filter scrubber after a full size scrubber on the inlet of the gearbox to protect the system and determine how much contamination the primary scrubber was missing.

RESULTS

After 3 years of operation there have been no gear or roller bearing failures (saving \$7,000 plus downtime), the oil cleanliness has improved and the life of the 10 micron conventional filters has been extended.



RECOMMENDED PRODUCT

**MAGNETIC FILTER
SCRUBBER**



403.242.4221





QUOTES@ONEEYEINDUSTRIES.COM

Photos show the amount of trapped contamination removed by the secondary scrubber from the system after 2 ½ years, showing that the majority of the contamination is being trapped by the primary magnetic filter.

The value of this gearbox is \$30,000 and a rebuild runs at \$7,000.

Analysis of the trapped contamination indicates that 6.88% was non-ferrous, 84.89% was ferrous and 8.23% was water. The photo at the right shows the bands of ferrous and non-ferrous contamination down to and below 3 microns.



Quantitative Results for: UJ7834 (1)

| Element Line | Net Counts | Weight % | Atom % |
|--------------|------------|----------|--------|
| C K | 4955 | 2.80 | 10.78 |
| O K | 19756 | 3.55 | 10.26 |
| Si K | 2544 | 0.59 | 0.98 |
| P K | 4724 | 1.15 | 1.72 |
| Ca K | 683 | 0.18 | 0.21 |
| Cr K | 1447 | 0.54 | 0.48 |
| Mn K | 2161 | 0.89 | 0.75 |
| Fe K | 203713 | 90.30 | 74.83 |
| Total | | 100.00 | 100.00 |



403.242.4221



QUOTES@ONEEYEINDUSTRIES.COM

