

CUSTOMER

PT. TJIWI KIMIA: PULP AND PAPER MILL LOCATION INDONESIA / JUL 2012 EQUIPMENT PULP MILL APPLICATION PULP SLURRY

PROVEN RESULTS



SLURRY PUMP PROTECTED WITHIN FIRST 8 HOURS OF OPERATION

CHALLENGE

Prevent the slurry pump and it's components from premature wear due to excessive bale wire contaminating the pulp slurry.


SOLUTION

Replace traditional magnetic filters with OEI filtration technology.

RESULTS

The photo shows substantial contamination, including bale wire, captured after 8 hours of operation.

After successful implementation, the mill has ordered multiple OEI filters to replace their previous magnetic filtration systems to protect the integrity of their equipment.





QUOTES@ONEEYEINDUSTRIES.COM

