



CASE STUDY

CUSTOMER

M/Y ALTAIR III

LOCATION

USA / 2007

EQUIPMENT

194 TRANSOCEANIC LUXURY YACHT 1974 AMELS

APPLICATION

DIESEL FUEL

PROVEN
RESULTSENGINE
PROTECTED

“ We mounted these because the year before we had quite a lot of problems with our fuel and lube systems due to water, metal and dirt. These magnetic filters have helped us considerably.”

- Captain

CHALLENGE

Capture wear contamination missed by the luxury vessel's existing filtration system and prevent it from prematurely wearing on fuel system components. The source of this contamination is the corrosion of transmission lines that carry the fuel to the end user.

SOLUTION

Install an OEI ADD-Vantage 9000 after the fuel centrifuge system.

RESULTS

The ferrous metal trapped on the magnetic filter shown in the photo represents 500 hrs of running time. This metal dust along with sludge is common of diesel fuel and water. If left in the fuel these metal particles will prematurely wear the injectors and fuel pump.



PRODUCT
RECOMMENDATION
ADD-VANTAGE 9000



403.242.4221



QUOTES@ONEEYEINDUSTRIES.COM

