



CASE STUDY

CUSTOMER

HOMAX OIL COMPANY

LOCATION

CASPER, WYOMING, USA / OCT 2009

EQUIPMENT

FILLING STATION PUMP

APPLICATION

LUBE OIL

PROVEN RESULTS



SAVED \$5,000
OF FILTER
REPLACEMENTS

“Had they not installed the OEI scrubber prior to the filter, the contamination captured by the OEI scrubber would have caused them to replace the filter elements twice at a cost of \$5,000. I feel the OEI scrubber paid for its self in this one test.”

- Ed Porter, Supervisor

CHALLENGE

Customer was concerned with the ISO quality of the oil being purchased. This is due to tighter tolerance on equipment, lubricants need to be cleaner.

SOLUTION

Install an OEI magnetic filter scrubber just before the filling station to the trucks.

RESULTS

A photo on the top right shows an installation prior to the filling station pump. The oil has been filtered by 6 micron filters before delivering to the customers in the past. Since the addition of the OEI scrubber to the filtering system, customers have noticed an increase in ISO cleanliness to their oils.

Homax Oil Co. seeing these results will be adding OEI scrubbers to all out going filling stations and also their incoming filtration system.

A photo on the bottom right shows the results of a new pipe line installation for unloading rail cars. An OEI scrubber was installed prior to the filtration system and the line was flushed with diesel fuel.



PRODUCT RECOMMENDATION

ADD-VANTAGE 9000



403.242.4221



QUOTES@ONEEYEINDUSTRIES.COM

